

BatteryShip.com

LIS1259 Sony Clie PEG-SJ30/U Battery Installation Instructions

PLEASE NOTE: Patience and care, along with moderate technical and hand tool ability, are required for the successful replacement of a Clie battery. **Excessive force may result in damage to your PDA.** The instructions below come with no warranty, guarantee, proper, or improper assembly or use. The instructions below come with no warranty or guarantee. By utilizing these instructions, you agree to hold Batteryship.com blameless and unaccountable for any and all damages, problems, or personal injuries that may or may not arise by your use of these instructions. Replacing your Clie battery may void any warranty you have on your Clie. **Please read all instructions and back up your data BEFORE replacing the battery.** If your Clie is a different model number, use these instructions as a reference and consult your owner's manual or a technician if necessary.

Included Phillips Screwdriver



Included Plastic Flathead Screwdriver



Step 1.



Remove the screw on the battery compartment, as shown, using the included Phillips screwdriver. (Your tool may look different than the picture shown.) Set the screw aside for reassembly.

Step 2.



Remove the battery compartment cover. Set the cover aside for reassembly.

Step 3.



Lift the main body of the battery out by pulling upward on the grey cloth tab, as shown. **Leave the connector plugged in for this step.**

Step 4.



Disconnect the old battery at the connector by placing the plastic flathead screwdriver on one side of the connector and twisting until that side comes out, then pull outward on the connector with your thumb and forefinger or tweezers. Be very sure that you are pulling outward on only the part of the connector that comes out, NOT on the whole connector.

(Steps 5 & 6 continued on back)

Step 5.



Making sure that your battery is facing the right direction (connector towards the top of the Clie), connect the new battery by pressing the connector at the end of the ribbon cable into the socket as shown. Note the location of the prongs in the socket of the Clie and the location of the plugs for the prongs on the battery connector, as well as the shape of the connector and the socket, and connect them accordingly. If the connector does not go in easily, try putting it in the opposite way. You may need to use the tip of the screwdriver or stylus to press the connector in, but **DO NOT** press too hard or try to force the pieces together. They will fit easily when correctly aligned. Position the new battery in its seat.

Step 6.



Replace the battery compartment cover and the screw. **FULLY CHARGE** your new battery before use. (Allow at least three hours. For quality control, we pre-charge many of our batteries, so yours may require less time.)

PLEASE NOTE: Our tools fit the majority of Clie's, but some devices may have different screws installed for various reasons. If our tools do not fit your device, you may have the appropriate tool in a tool kit you already own. You can also check your local hardware or electronics store if you do not have the right tool at home.